

**New England East-West Solution (NEEWS)
Greater Springfield Reliability Project**

**Drainage Analysis for the
Newgate/Phelps Road and the Hatchett Hill Road
Areas**

prepared for

Northeast Utilities

January, 2011

Rev. 1

prepared by

**Burns & McDonnell Engineering Company, Inc.
Wallingford, Connecticut**

TABLE OF CONTENTS

	<u>Page No.</u>
1.0 OBJECTIVES	1-1
2.0 PROJECT DESCRIPTION	2-1
3.0 INTRODUCTION	3-1
3.1 Newgate/Phelps Road Area, East Granby and Suffield	3-2
3.1.1 Public Comments	3-2
3.2 Hatchett Hill Road Area, East Granby	3-3
3.2.1 Public Comments	3-3
4.0 RUNOFF CHARACTERISTICS & FLOW CALCULATIONS	4-1
4.1 Two-, Ten-, and Fifty-Year Storm Event Calculations	4-2
4.1.1 Newgate/Phelps Road Area	4-2
4.1.2 Hatchett Hill Road Area	4-5
5.0 SURFACE WATER CONTROL MEASURES	5-1
5.1 Vegetation Removal	5-1
5.2 Newgate/Phelps Road Area Surface Water Control	5-3
5.2.1 Silt Fence	5-4
5.2.2 Stone Check Dam	5-5
5.2.3 Summary	5-5
5.3 Hatchett Hill Road Area Surface Water Control	5-6
5.3.1 Silt Fence	5-8
5.3.2 Summary	5-8
6.0 CONCLUSION	6-1

LIST OF TABLES

<u>Table No.</u>	<u>Page No.</u>
Table 4-1 Two-Year Storm Event	4-3
Table 4-2 Ten-Year Storm Event	4-3
Table 4-3 Fifty-Year Storm Event	4-4
Table 4-4 Two-Year Storm Event	4-5
Table 4-5 Ten-Year Storm Event	4-5
Table 4-6 Fifty-Year Storm Event	4-6

LIST OF APPENDICES

- APPENDIX A SITE DRAWINGS
- APPENDIX B TYPICAL EROSION CONTROL MEASURE DETAILS